

## Tip of the Week – Preventing Risk



**CASE STUDY #1:** PaSea H.EL.M.E.T. Marine Risk Assessment

**RISK ELEMENT:** Mooring Tail

**MRA FINDING:** 20 mooring tails on service for more than 30 months without any evidence of regular checking

**AS PER CP 25-PARA 3.9, MOORING TAILS SHOULD BE REPLACED  
MAX EVERY 18 MONTH INTERVALS**

This period may be much less for a vessel engaged in lightening.  
Life span of a tail may be greater than 18 months, depending on the use and  
therefore need to be carefully checked after each use.

**Making Prevention A HABIT!**