



## Tip of the Week – Preventing Risk



**CASE STUDY #28** PaSea H.EL.M.E.T. Marine Risk Assessment

**RISK ELEMENT:** Deck Condition

**MRA FINDING:** A number of the bolts on the Helicopter area's collapsible side rails were observed to be too tight for quick loosening

### REF. SOLAS II-2/18

THE CONDITION OF THE FALLING RAILS AFFECTS POTENTIAL HELICOPTER OPERATION THAT MAY BE CARRIED OUT ONBOARD. THE QUICK DISMANTLING OF COLLAPSIBLE RAILS IS VITAL IN CASE OF AN EMERGENCY LANDING OF A HELICOPTER.

INSPECTION AND MAINTENANCE AT REGULAR TIME INTERVALS AS PER COMPANY'S PMS SHOULD BE DONE IN ORDER TO ENSURE PROPER DECK CONDITION.

## Making Prevention A HABIT!