



Tip of the Week – Preventing Risk



CASE STUDY #9 PaSea H.EL.M.E.T. Marine Risk Assessment

RISK ELEMENT: Catering

MRA FINDING: The drain system in the Galley was not working properly due to clogged spouts.

REF. MLC requirement (MLC 3.1)

Despite of a serious matter of hygiene, it is an indicator of wellbeing on-board which, additionally, can lead to a negative impression from PSC Officers and other Inspectors attending the vessel.

IT IS SUGGESTED THAT HIGH PRIORITY IS GIVEN TO MATTERS OF HYGIENE IN THE ACCOMODATION SPACES AND ESPECIALLY THE VESSEL'S GALLEY

Making Prevention A HABIT!