



Tip of the Week – Preventing Risk



CASE STUDY #20 PaSea H.EL.M.E.T. Marine Risk Assessment

RISK ELEMENT: Catering - Precautions

MRA FINDING: Although the temperature checklist was posted on the Provision Fan Panel, the standard temperatures for each refrigerator chamber were not mentioned.

REF. MLC 3.1, TMSA 3A.1.2

IT IS VERY IMPORTANT THAT THE CREW HAVE THE MOST SENSITIVE INFORMATION RELATING TO EQUIPMENT ONBOARD READILY AVAILABLE TO THEM.

IT IS STRONGLY RECOMMENDED THAT THE STANDARD TEMPERATURES FOR EACH REFRIGERATOR ARE POSTED ON THE PROVISION FAN PANEL IN ORDER FOR THE CREW TO BE FULLY AWARE OF THEM & BE IN A POSITION TO IDENTIFY MALFUNCTIONS.

Making Prevention A HABIT!